

CASE EXAMPLE

PHARMACEUTICAL PLANT FLOOR COATING ON A CRACKED CONCRETE SLAB

Customer and prime contractor : SANOFI PASTEUR

Company : KEMICA

workplace : VAL DE REUIL - France

Date of work realisation : July - August 2007

Works :

- *Pharmaceutical plant floor coating*
- . grinding, dedusting of a cracked concrete slab
- . cracks filling up with resin
- . application of concrete primer P201
- . application of SOUPLETHANE 5, thickness 2,5 mm reinforced with glass fabric 450 g/m²

Technical interest :

- resists strongly to mechanical shocks
- resists to cracks of concrete substrate
- dust free coating, can easily be cleaned
- resists to demineralised water

